



1. Determine location of part
2. Decide on fixing method
3. Fixing methods are
  - "H" - Side mount (use BHCS)
  - "I" - Bottom mount (use SHCS)
  - "J" - Through hole (use SHCS)
4. Only required to use hole centres relative to fixing method

